

<b>ID</b>	<b>74</b>
-----------	-----------

<b>Category:</b>	<b>Parking</b>
<b>Location:</b>	<b>Typical of site access roads and parking areas</b>
<i>Satisfactory:</i>	<input type="checkbox"/>
<i>Damaged:</i>	<input type="checkbox"/>
<i>Condition Code:</i>	
<i>Condition Description:</i>	
<i>Comments:</i>	Typical layering of asphalt over concrete surfaces for roads and parking areas.

Survey Date 03/27/00



ID 75

**Category:**

**Parking**

**Location:**

**Archives Building**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:* Handicap parking with ramp adjacent to door.

Survey Date 06/01/00



**ID**    **76**

**Category:**

**Parking**

**Location:**

**NW corner behind State Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Asphalt, good condition. Note limited parking and unaesthetic location adjacent to Capitol building.

Survey Date    06/01/00



ID 77

**Category:**

**Parking**

**Location:**

**West of parking garage, NW parking area**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Non-standard handicap stalls, only regular stalls signed as handicap.

Survey Date 03/24/00





ID 78

**Category:**

**Parking**

**Location:**

**West of State Office Bldg, NW parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Asphalt, good condition. Note lane widths are narrow in this parking area, difficult for larger vehicles.

Survey Date 03/24/00



ID 79

**Category:**

**Parking**

**Location:**

**NW parking area, adjacent to State Office Bldg**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Typical bus access to State Office Building on right edge of pavement. Asphalt patches typical of all parking areas.

Survey Date 06/01/00



**ID**    **80**

**Category:**            **Parking**  
**Location:**            **NW parking area, looking west**

*Satisfactory:*            ☐

*Damaged:*              ☐

*Condition Code:*        **O**

*Condition Description:*    **Other (describe)**

*Comments:*              Entrance from Columbus Street -- no striping as to which travel lane to drive in or which area to park in.

Survey Date    06/01/00



**ID**    **81**

**Category:**

**Parking**

**Location:**

**Greenhouse Facilities**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Difficult maneuvering through poles for fire truck access to hydrant.

Survey Date    03/24/00



<b>ID</b>	<b>82</b>
-----------	-----------

<b>Category:</b>	<b>Parking</b>
<b>Location:</b>	<b>Greenhouse Facility, from 500 North</b>
<i>Satisfactory:</i>	<input type="checkbox"/>
<i>Damaged:</i>	<input type="checkbox"/>
<i>Condition Code:</i>	O
<i>Condition Description:</i>	Other (describe)
<i>Comments:</i>	Limited parking.

Survey Date 06/01/00





ID 83

**Category:**

**Parking**

**Location:**

**Small parking area east of Data Proc. Center**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:* Faded striping, some loose gravel

Survey Date 06/01/00



**ID**    **84**

**Category:**

**Parking**

**Location:**

**NE of State Office Bldg, Upper East  
parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Standard travel lane into parking area.

Survey Date   06/01/00



**ID**    **85**

**Category:**                    **Parking**  
**Location:**                   **NE corner of Upper East parking area**

*Satisfactory:*                ☐

*Damaged:*                    ☐

*Condition Code:*            **O**

*Condition Description:*   **Other (describe)**

*Comments:*                   Parking area used for soil and dumpster storage  
in spring/summer, snow storage in winter.  
Relocate these types of storage. Clean up  
soiled asphalt.

Survey Date   06/01/00



**ID**    **86**

**Category:**

**Parking**

**Location:**

**Middle East parking area, looking north**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



ID 87

**Category:**

**Parking**

**Location:**

**Middle East parking area (for buses)**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Close to access to East Capitol Blvd. and to the Capitol building.

Survey Date 06/01/00





**ID**    **88**

**Category:**

**Parking**

**Location:**

**Lower East parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*                      Asphalt, good condition, with handicap stalls.

Survey Date    06/01/00



ID 89

**Category:**

**Parking**

**Location:**

**Loop road to Lower East parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00



ID 90

**Category:**

**Parking**

**Location:**

**Loop road at front of Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Asphalt, good condition. Note limited and unaesthetic parking location.

Survey Date 06/01/00



ID 91

**Category:**

**Parking**

**Location:**

**Entrance to SW parking area**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

EX

*Condition Description:*

Exfoliated or spalled surface; needs repair and correction of water

*Comments:*

Asphalt deterioration due to poor drainage, loose gravel.

Survey Date 03/23/00



ID 92

**Category:**

**Parking**

**Location:**

**SW parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Good condition. Large asphalt parking area for monument or D.U.P. Museum access.

Survey Date 06/01/00





**ID**    **93**

**Category:**

**Parking**

**Location:**

**Loop road parking in front of Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Asphalt, good condition. Note limited parking and unaesthetic location.

Survey Date    06/01/00



**ID**    **94**

**Category:**

**Parking**

**Location:**

**West Entrance to Capitol, between sets of stairs**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Asphalt deterioration, loose gravel along parallel parking stalls.

Survey Date    03/23/00



**ID**    **95**

**Category:**

**Parking**

**Location:**

**West of Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Asphalt, good condition, no stripping. Note large asphalt area, adjacent to the Capitol building.

Survey Date    06/01/00



**ID**    **96**

**Category:**

**Curb/Gutter**

**Location:**

**NE corner Data Processing building, near  
Archives**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Elevated wall to the right of hydrant limits  
access to hydrant for fire crews.

Survey Date   06/01/00



**ID** 97

**Category:**

**Curb/Gutter**

**Location:**

**Entrance to NE parking area from 500 North**

*Satisfactory:*



*Damaged:*



*Condition Code:*

EX

*Condition Description:* Exfoliated or spalled surface; needs repair and correction of water

*Comments:*

Survey Date 03/24/00





**ID**    **98**

Survey Date    03/24/00

**Category:**

**Curb/Gutter**

**Location:**

**Small gravel parking area east of Data Process.**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:*    Other (describe)

*Comments:*

Gravel from parking lot washes down waterway into gutter. Clean loose gravel from lot to keep gravel from entering storm drain system.



ID 99

**Category:**

**Curb/Gutter**

**Location:**

**East Capitol at entrance to east Capitol parking**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Single functioning catch basin for all NE parking areas, not bicycle safe. Replace with bicycle safe grate.

Survey Date 03/24/00



**ID**    **100**

**Category:**                    **Curb/Gutter**  
**Location:**                   **Middle East parking area east of Cafeteria**

*Satisfactory:*                ☐

*Damaged:*                   ☒

*Condition Code:*           **BR**

*Condition Description:*   **Broken , severely cracked or  
chipped, needs repair or**

*Comments:*

Survey Date   06/01/00



ID 101

**Category:**

**Curb/Gutter**

**Location:**

**Entrance to Lower East Capitol parking area**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

C

*Condition Description:* General Cleaning Needed

*Comments:*

Non-functioning catch basin around corner from non-bicycle safe catch basin mentioned previously.

Survey Date 03/24/00





**ID**    **102**

**Category:**

**Curb/Gutter**

**Location:**

**Middle East parking area, near Cafeteria**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

BR

*Condition Description:* Broken , severely cracked or  
chipped, needs repair or

*Comments:*

Survey Date   03/24/00





**ID**    **103**

**Category:**

**Curb/Gutter**

**Location:**

**Entrance to Middle East parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

BR

*Condition Description:* Broken , severely cracked or  
chipped, needs repair or

*Comments:*

Survey Date    03/24/00



**ID**    **104**

**Category:**

**Curb/Gutter**

**Location:**

**Access road on east side of Capitol**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

BR

*Condition Description:*

Broken , severely cracked or  
chipped, needs repair or

*Comments:*

Curb damage, asphalt deterioration at edge of  
gutter.

Survey Date    03/23/00



**ID** 105

**Category:**

**Curb/Gutter**

**Location:**

**SE corner of Capitol, access road**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Curb and gutter suddenly end forcing drainage onto access road. Reevaluate gutter flow.

Survey Date 03/23/00



**ID**    **106**

**Category:**

**Curb/Gutter**

**Location:**

**Parallel parking loop, near 300 North**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date   03/27/00



**ID** 107

**Category:**

**Curb/Gutter**

**Location:**

**Parallel parking loop adjacent to 300 North**

*Satisfactory:*



*Damaged:*



*Condition Code:*

EX

*Condition Description:*

Exfoliated or spalled surface; needs repair and correction of water

*Comments:*

Gravel and debris plugging drain -- needs cleaning.

Survey Date 06/01/00





**ID**    **108**

**Category:**

**Curb/Gutter**

**Location:**

**Parallel parking loop at 300 North, looking west**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Typical rough edge of pavement with gutter.  
Observe for large erosion areas that release gravel into storm drain system.

Survey Date    06/01/00



**ID**    **118**


Survey Date   03/23/00

**Category:**                    **Curb/Gutter**  
**Location:**                   **NW parking area (west edge)**

*Satisfactory:*                ☐  
*Damaged:*                   ☒  
*Condition Code:*            BR

*Condition Description:*   Broken , severely cracked or  
   chipped, needs repair or

*Comments:*



**ID** 109

**Category:** Curb/Gutter  
**Location:** 300 North west of State Street

**Satisfactory:** ☐

**Damaged:** ☒

**Condition Code:** EX

**Condition Description:** Exfoliated or spalled surface; needs repair and correction of water

**Comments:** Erosion due to high velocity storm runoff. Repair asphalt.

Survey Date 03/23/00



**ID** 110

Survey Date 03/27/00

**Category:** Curb/Gutter

**Location:** 300 North

*Satisfactory:* ☒

*Damaged:* ☐

*Condition Code:* O

*Condition Description:* Other (describe)

*Comments:* Surface flow, to piped flow, then returned to gutter flow. Investigate reason for transition of flow.



**ID**    **111**

**Category:**

**Curb/Gutter**

**Location:**

**Southwest parking area**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

EX

*Condition Description:* Exfoliated or spalled surface; needs repair and correction of water

*Comments:* Repair asphalt.

Survey Date 03/23/00





ID 112

**Category:**

**Curb/Gutter**

**Location:**

**Adjacent access road on west side of Capitol**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Curb and gutter disconnect. Reevaluate runoff direction, redesign gutter where applicable.

Survey Date 06/01/00



ID 113

**Category:**

**Curb/Gutter**

**Location:**

**Access road at SW corner of Capitol**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

EX

*Condition Description:*

Exfoliated or spalled surface; needs repair and correction of water

*Comments:*

High point in gutter cuts off flow. Recommend replacement of approximately 150 feet of curb and gutter.

Survey Date 03/23/00



**ID**    **114**

**Category:**

**Curb/Gutter**

**Location:**

**Access road at SW corner of Capitol**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

BR

*Condition Description:*

Broken , severely cracked or  
chipped, needs repair or

*Comments:*

Exit pipe appears broken, sharp edge exposed.

Survey Date    03/27/00



ID 115

**Category:**

**Curb/Gutter**

**Location:**

**Adjacent to access road on west side of Capitol**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

*Condition Description:*

*Comments:*

Noted possible end to roof drain, could not open.

Survey Date 03/27/00





<b>ID</b>	<b>116</b>
-----------	------------

<b>Category:</b>	<b>Curb/Gutter</b>
<b>Location:</b>	<b>West lawn</b>

<i>Satisfactory:</i>	<input checked="" type="checkbox"/>
----------------------	-------------------------------------

<i>Damaged:</i>	<input type="checkbox"/>
-----------------	--------------------------

*Condition Code:*

*Condition Description:*

<i>Comments:</i>	Noted bubble up box on west lawn.
------------------	-----------------------------------

Survey Date 03/27/00





**ID** 117

**Category:**

**Curb/Gutter**

**Location:**

**Entrance to NW parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Outlet from parking area, discharges to gutter flow. Curb and gutter in good condition.

Survey Date 03/27/00



**ID** 119

**Category:** Curb/Gutter  
**Location:** NW parking area (south edge)  
**Satisfactory:** ☐  
**Damaged:** ☒  
**Condition Code:** BR  
**Condition Description:** Broken , severely cracked or chipped, needs repair or  
**Comments:** Replace approx. 30 feet of curb.

Survey Date 06/01/00

